CHECK	MATERIALS NEEDED FOR <u>OMEGA</u> FENCE	Comments
	OMEGA BRACKETS 1mm	Intermediate pole, placed every 3m
	OMEGA BRACKETS 2mm	Corner poles, placed every 50m, Change in direction and either side of the Gates
	CORNER STAYS	If required above the pallisade or wall
	OMEGA CLIP ON BOBBINS	Only for the 1mm bracket, 1 for each line of fence, eg 1.2m omega takes 12 insulators
	TENSIONERS	Only for the 2mm bracket, 1 for each line of fence, eg 2mm 1.2m omega takes 12 tensioners
	STRAINERS	Only for the 2mm bracket, 1 for each line of fence, eg 2mm 1.2m omega takes 12 Strainers
	WIRE	Use the lentgh of the fence multiply by the amount of lines, eg 100 x 20 lines
	S-HOOKS	Dependant of the pole, s- hooks or 90 deg hooks or 180 deg hooks
	FERRULES	If required, double the amount of springs and hooks
	LINE CLAMPS	If required, for joints and loops
	EARTH SPIKES	Placed every 30m of fence line plus 3 for the energizer
	WARNING SIGNS	Placed every 10m of fence line, gates and change of direction
	GATE CONTACT & BRACKET	1 per gate to carry over power
	ACCESSORIES FOR GATE	Brackets, tensioner, hooks strainer ect
	ENERGIZER	Model, 1 zone or 2 zone ect
	KEYPAD	To match energizer
	SIREN	Max 30w siren
	ENCLOSURE (OUTSIDE)	Steel or Fibre glass
	STROBE & MOUNTING BRACKET	1 per zone
	COMMS CABLE	100m rolls only
7	FENCE LIGHT	Max 3 per fence
	CONDUIT ACCESSORIES	If required
	CONCRETE	If required
	LOOPS	If required
	TOOLS	If required
	LIGHNING DIVERTERS	2 per zone